© Site Engineering Personnel Limited 2009
Reproduction in whole or in part by any means is prohibited without the prior permission of Site Engineering Personnel Limited.



SECTION LOCATION PLAN

BUILDING SURVEY LEGEND

Level Prefix Descriptions

SL00	Spot Level
FL00.00	Floor Level
CL00.00	Ceiling Level
CD00.00	Underside of Ceiling Level
UB00.00	Underside of Beam
TL00.00	Top Level
GR00.00	Gut Level
TB00.00	Top of Beam
LL00.00	Lower Level
AB00.00	Arch Bottom Level

Symbol Descriptions

00.00	Level Marker
00.00	Level Marker
	Stairs/Ramp Direction
	Display Ceiling Direction

Linetype Descriptions

	Big Bolts
	Big Bolts Partition
	Big Bolts Complete
	Cladding
	Dimensions
	Doors
	Ceiling
	Excavation
	Fire Appliance
	Hospitals
	Hotels
	Information Centre
	Kitchen Furniture
	Lecture Halls
	Lighting
	Office Plan
	Or Drains
	Pipework
	Plants
	Sanitary
	Sections
	Sculpture
	Shelving
	Stairs/Walks
	Surface Changes
	Tables
	Trees
	Walls
	Wall Cavities
	Windows
	Hidden Detail

Symbol Descriptions

	Radiator
	Break Line
	Door Swing
	Toilet
	Urinal
	Sink
	Kitchen Sink

Deviation Diagram

Figure show deviation of ceiling from area. Ceiling deviation is measured from the ceiling plate and area defined at position marked on area etc.



Datum 177.00m

Section A–A'



Datum 177.00m

Section B–B'



Datum 177.00m

Section C–C'



Datum 177.00m

Section D–D'

Datum 177.00m

Section E–E'

Datum 177.00m

Section F–F'

Datum 177.00m

Section G–G'



Datum 177.00m

Section H–H'



All levels relate to O.S.B.M Located on the corner of the Church. Value 180.01m.

LAND SURVEYING • ENGINEERING SURVEYING • LASER SCANNING
BUILDING SURVEYING • SITE ENGINEERING • UTILITY SURVEYING

Client

Project Title

BUILDING CROSS SECTION

Scale	Date	Job No
Surveyed	Drawn	Checked

Survey & Engineering Projects, 33 Sandy Lane, Skelmersdale, Lancashire, WN8 8LA
T. (01695) 726620 F. (01695) 722696 W. www.sepltd.com E. info@sepltd.com